

From: ["Wallingford, Jonni B." <wallingfordjb@cdmsmith.com>](mailto:Wallingford, Jonni B. <wallingfordjb@cdmsmith.com>)
To: ["Zhen, Davis" <Zhen.Davis@epa.gov>](mailto:Zhen, Davis <Zhen.Davis@epa.gov>)
["Sheldrake, Sean" <sheldrake.sean@epa.gov>](mailto:Sheldrake, Sean <sheldrake.sean@epa.gov>)
CC: younghs@cdmsmith.com
["Scott Coffey" <coffeyse@cdmsmith.com>](mailto:Scott Coffey <coffeyse@cdmsmith.com>)
Date: 7/30/2018 2:05:46 PM
Subject: Subsurface sediment coring
Attachments: [Snapchat-264489055.jpg](#)
[Snapchat-1001841390.jpg](#)
[Snapchat-465741223.jpg](#)

Afternoon,

Attached photo of SC-S062 (RM 4.6W) southeast of Linnton Plywood property line, attempt #1. Core yielded a 50% recovery. The Pre-RD group plans to core another sample in attempts to gain more recovery. Meanwhile, the first core is placed on ice immediately after coring.

Jonni (b) (6)

Get Outlook for Android<<https://aka.ms/ghei36>>